



For full credit, ICT Dollar Bill Acceptors need to be returned with the power cable shown in the photo. The cable has a 9-pin square connector on one end, and a 30-pin rectangular connector on the other, with two pins blocked off.

Partial credit—less the price of this cable, will be issued for DBAs returned without it. This cable can now be ordered as part # 880200155, if needed.

The black cable seen on the lower part of the DBA in this photo is permanently attached, and not removable.

Return to:  
Valley-Dynamo  
7224 Burns Road  
RMA # \_\_\_\_\_

(reference the RMA number provided, returns without RMA numbers may be delayed or refused)

Richland Hills, TX 76118



Thanks,  
Valley-Dynamo Parts and Service